

Service History Listing Active Units

Date: 10/06/2026

Time: 4:16:14PM

For Equipment Code From: H14485 To: H14485
 For Date Posted From: All To: All
 Don't Show Cost

For Customer Code From: All To: All
 For Branch Code From: All To: All

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1824523	get operational & clean for Auction - ready to go		8/05/2026	Internal	7310.0	\$0.00	-Locate unit -Get Unit Operational(Unit starts and drives) -Unit has Next to NO BRAKES -Steam Clean Unit -Take Photos READY FOR AUCTION
1727457	Scheduled Service - JM SM IC 500Hr Service .0500 Hour Service		30/07/2025	Internal	340193.0	\$0.00	Prepare For Sale - Workshop
1709612	Seatbelt locks in but the dashboard doesn't register. Urgent. ETKT-1076137		30/04/2025	Internal	7301.0	\$0.00	TRAVEL OFFSITE MULTIPLE TIME FIRST TIME WAS DIAGNOSIS AND TEMP REPAIR NEW TIME WAS FIT SEAT AND RE CONFIGURE WIRING TO SUIT NEW SEAT
1682267	Has been sent to Bridgestone for new steer tyres. The brakes on this forklift are also in need of repair as the pedal travels a long way down before engaging the brakes. - etkt#971767		25/03/2025	Internal	340193.0	\$0.00	Job completed by North Point Mechanical travel offsite set up work area once vehicle supported on stands remove front wheels remove front hub assembly. removes brake assembly remove wheel cylinders replace all shoes wheel cylinders , breatings and races , new axle seals , new brake master cylinder . full adjustment completed and bleed of air out of system . test functions and braking once back together
1684911	* 12/5 * Scheduled Service - KM IC 1000hr SM - 5000hrs .1000 Hour Service		27/02/2025	Internal	340193.0	\$0.00	
1621368	3G Sunset - Replace FM1 Kit for VAM kit		1/09/2024	Internal	6939.0	\$0.00	Replace Fleet Management System as required, Carried out FM1 to VAM swap. Carried out online setup & tested all functions. Successful. Completed

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1647686	Scheduled Service - KM IC 500hr SM - 4500hrs .0500 Hour Service		31/08/2024	Internal	6939.0	\$0.00	Travel to site, Steam clean equipment as necessary. Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Carried out 500HR service. Jack up, grease & check over. High pressure clean unit due to excessive dust. Remove and lubricate accelerator cable due to dirt causing stiffness of acceleration and also jamming, FW Required;; -Steer pins and bushes worn. -Fan belt requires replacing. -Steering wheel knob faulty. -Diff pinion seal leaking. Job Completed by Bridgestone tyres
1642503	Needs new pneumatic steer tyres. Forklift left at Bridgestone. Etkt 817238		23/07/2024	Internal	5564.0	\$0.00	W/ORDER: 023348 ASSET # H14485 (CENTURION FREIGHT) tyres replaced. Job Completed by NPIS
1470400	*PARTS ORDERED 12/02/24* Scheduled Service - KM IC 4000hr SM - 4000hrs .4000 Hour Service		18/03/2024	Internal	5564.0	\$0.00	Carried out 4000 hr service Replaced all fluids Replaced all oils Brake fluid changed Replaced drive belt Adjusted chaines -lubricated chaines Adjusted brakes re packed wheel bearings Service notes Diff to Gearbox driveshaft seal is leaking of diff side requires new seal. Drivebelt supplied in kit was about 20mm to small even with alternator completely de adjusted, couldn't make it fit. when changing fuel filter lots of small metal flakes were present , Tank may be starting to break up on bottom of tank. Mast lift chaines were very rusty this asset had not been serviced for a while . Job Completed by Bridgestone Tyres 12/03/24
1605054	All tyres to be replaced. Etkt 680379	SUBC-RNT60102	12/03/2024	Internal	6586.0	\$0.00	Job Completed by Bridgestone Tyres 12/03/24 Supply and replaced tyres

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1599876	Unit is only going 7 kmph which is not enough to get up ramp trailer. Etkk 660464		12/02/2024	Internal	6586.0	\$0.00	
1574513	Accelerator not working. Etkk 566285		25/01/2024	Internal	6586.0	\$0.00	Job Completed by North Point Mechanical. Traveled to site initially found no acceleration at all Attempted to try separating from fork trac back to factory did not work Removed foot tray and pedal checked potentiometer test with multimeter, seemed to range ok didnt have actual specs off factory . Checked wiring harness to Pedal and found had no signal at all to pedal . Had earth but no signal Checked all fuses etc Could not find anything blown, asked Adapalift for wiring diagram or tech support. Fork then Sat down for long period of time approx 2 months Re attended site once a manual pedal was sent up. Removed old electronic actuator and pedal and discarded HAd to replace Battery as it was completely discharged . Replaced fuel filter as it was previously removed off this fork and used to get another going previously . Job Completed by NPIS
1567939	FW: Order & Replace brake shoes and wheel cylinders		15/12/2023	Internal	6425.0	\$0.00	Travel to site Drive fork on ramps Jack front axle remove front wheels Remove brake drum and brake components Replace with new supplied parts Bleed and adjust brakes Re fit wheels and torque to spec Road test This Job was completed Job completed by North Point Mechanical.
1557007	Unit has a disintegrated seatbelt holder and this is a brand new one, so something is faulty.(pics to sc) Etkk 504193		28/08/2023	External	6396.0	\$277.14	Service Report: Travel to site identified that latch assembly been broken , removed seat belt latch off spare seat and wired up -function tested ok .

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1551239	Brake fluid leak. Etkt 480399		8/08/2023	Internal	6396.0	\$0.00	Job completed by North Point Mechanical Traveled to site topped up brake fluid , Inspected for leaks Adjusted brakes Suggest next major service we order brake shoes and wheel cylinders for replacment.
1553657	Accelerator not working properly. ETKT 490471		3/08/2023	Internal	6396.0	\$0.00	
1536449	Flat/puncture Drive tyre (ref job 1517900)		22/05/2023	External	6396.0	\$206.09	
1528352	Seat belt latch is broken-Tagged Out-URGENT-ETKT-391121		17/04/2023	Internal	6490.0	\$0.00	inspected vehicle - requires new seat belt latch as current one is perished Please send buckle and wiring assembly
1519270	Has de-rated and only drives at 2kmp/hr with the occasional surge to 7kmh. Tagged Out. URGENT-PTKT-353663		8/03/2023	Internal	6396.0	\$0.00	CHECK NO POWER AND SPEED ONLY GOING 2KM. CHECK FUEL SYSTEM, OK. TEST DRIVE, ENGINE RUNS FINE THEN CUTS OUT. INTERMITTENT THROTTLE, CHECK PEDAL. REMOVE FLOOR PANEL AND FOUND SQUASHED WIRES UNDER PEDAL INSIDE LOOM. INSPECT NOT BROKEN, MOVE AND SECURE. FOUND PLUG IN PEDAL LOCK BROKEN, P-CLAMP TO SECURE. TEST DRIVE, FAULTED AGAIN. REMOVE THROTTLE MOTOR AND CHECK HARNES AND PIN. FOUND RUBBED WIRING AND LOOSE PIN IN PLUG. REPAIR WIRING AND PIN. TEST DRIVE, OK.
1517900	INSPECTION ONLY - flat drive tyre. - ETCK 348016		2/03/2023	Internal	6088.0	\$0.00	
1506139	Seatbelt and underseat wiring issue etkt #300579		10/01/2023	Internal	6088.0	\$0.00	FIT NEW SEATBELT AND BUCKLE TO FORKLIFT. CUT AND SOLDER WIRES, SECURE CONDUIT AND CABLE TIED IN POSITION. OPERATION TESTED OK.
1503109	The unit needs two new tyres. THE UNIT IS LOCATED AT THE BRIDGSTONE IN BROOME. ETKT-291227		20/12/2022	Internal	6088.0	\$0.00	
1480485	Won't start or jump start, maybe could be the starter motor. Tagged Out. URGENT. ETKT-215326		20/09/2022	Internal	6088.0	\$0.00	
1475860	Inspect tyres - may need to be changed. Etkt 201253		30/08/2022	Internal	5959.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1470958	The unit will not start and won't jump start. Appears to be the battery. Tagged Out. URGENT. PTKT-188867		10/08/2022	Internal	5959.0	\$0.00	Subby Broome Diesel attend ed site: CHECK AND REPAIR FORKLIFT NOT STARTING. REFIT BATTERY TO MACHINE. START MACHINE AT STARTER MOTOR. CHECK IGNITION SYSTEM AND IDENTIFY FAULT AT SEAT SWITCH. SECURE SWITCH IN POSITION AND TEST, OK. RETURN TO WORKSHOP. Job Complete
1440842	under the seat sensor, sometimes the fork will start and other it wont - SF EMAIL - URGENT		25/03/2022	Internal	5564.0	\$0.00	REPAIR INTERMITTENT STARTING FAULT, CHECK SEAT AND SEATBELT SWITCHES. FORKTRAC SCREEN UNIT FAULTY. REMOVE, SWAP SCREEN UNIT WITH ANOTHER FORKLIFT AND TEST OPERATION, OK. FITTED NEW SCREEN WHEN PART ARRIVED AND REFITTED TEST SCREEN TO ORIGINAL FORKLIFT, TEST OPERATION, OK. REPLACED RHS MIRROR
1425788	Unit keeps shutting down, possibly fuel filter or electrical. URGENT. SF EMAIL		17/01/2022	Internal	5493.0	\$0.00	Broome Diesel attended site: 18/01/22 CHECK ENGINE FAULT. REMOVE AND INSPECT FUEL FILTER FOR CONTAMINATION. REPLACE FUEL FILTER/COALESCOR FILTER AND PRIMARY INLINE FILTER. PRIMER PUMP LEAKING AIR INTO FUEL SYSTEM. FIT INLINE FILTER TO BYPASS FAULTY FILTER HOUSING.CHECK FUEL SUPPLY NOT CONTAMINATED, REPLACE WITH SECOND FOR TEMPORARY FILTRATION. 07/02/22 REMOVE AND REPLACE FUEL FILTER HOUSING AND FILTER ASSEMBLY. REPLACE SECONDARY FUEL FILTER. BLEED SYSTEM AND TEST RUN, WASH DOWN. Job Complete
1422873	Solids have been sent back and would like pneumatics		23/12/2021	Internal	5312.0	\$0.00	
1412427	Customer would like Pneumatic tyres for this unit		4/11/2021	Internal	5312.0	\$0.00	
1411253	Unit has a rattle in brake area. Tagged out. URGENT		28/10/2021	Internal	5312.0	\$0.00	Subby attended site - Broome Diesel: CHECK REPORTED RATTLE IN DRIVELINE. JACK MACHINE UP AND CHECK DRIVELINE, IDENTIFY BENT GAURD CONTACTING DRIVESHAFT. REPAIR GAURD AND DELIVER MACHINE TO DEPOT. Job Complete

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1391571	Scheduled Service - 500 Hour Service .0500 Hour Service		6/10/2021	Internal	5278.0	\$0.00	Subcontractor - Broome Diesel attended site: Completed a 500hr service. Job Complete
1403825	Unit has 3 stripped wheel studs. See notes. URGENT. SF EMAIL		23/09/2021	Internal	4533.0	\$0.00	Subby - Broome Diesel attended site: 3 X RHS STEER WHEEL STUDS ARE STRIPPED, MAKE TEMPORARY REPAIR. LIST OTHER STEERING AND SEAT BELT PARTS REQUIRED AND ORDER PARTS. 05/10/2021 REMOVE AND REPLACE X 6 STUDS AND NUTS. REFIT WHEEL AND TENSION WHEEL NUTS. FIT WHEEL NUT RETORQUE STICKER TO DASH. REMOVE AND REPLACE SEAT BELT. CONNECT SEAT BELT SWITCH WIRING. REMOVE AND REPLACE STEERING LINK PINS AND BUSHES. LUBE STEERING. CLEAN DOWN Job Complete
1391180	New solid tyres required. SF EMAIL		23/07/2021	Internal	4533.0	\$0.00	
1359936	Scheduled Service - RH. 1000Hr service .1000 Hour Service		23/02/2021	Internal	4533.0	\$0.00	
1335415	Riased for part to be transferred off job 1295262 so we can close that job.		22/10/2020	Internal	4533.0	\$0.00	
1330939	Hydraulic leak from tyne side shift - SF Email		30/09/2020	Internal	4533.0	\$0.00	Subcontractor - Broome Diesel attended site: CHECK AND REPAIR HYDRAULIC OIL LEAKS FROM TYNE SIDESHIFT ASSEMBLY. REPLACE HYDRAULIC HOSES ON SIDE SHIFT. TOP UP HYDRAULIC OIL LEVEL. DEGREASE AND PRESSURE WASH. TEST OPERATION AND CHECK FOR LEAKS. RETURN FORKLIFT TO CUSTOMER SITE. Job Complete
1300076	Handbrake adjusted please as it engaged all the time making the forklift difficult to drive - SF Email.		21/05/2020	Internal	4092.0	\$0.00	Subcontractor - Broome Diesel attended site and adjusted the brakes and the pedal push rob. Job Complete
1297767	Remove speed limiting kit		13/05/2020	Internal	4086.0	\$0.00	
1296871	Cancelled - Scheduled Service - RH. 500Hr service .0500 Hour Service		8/05/2020	Internal	4086.0	\$0.00	
1295262	Replace Fork Positioner Ram		4/05/2020	External	4031.0	\$522.00	
1286246	FW: Seat switch is faulty, steering joints all worn out		24/03/2020	Internal	2989.0	\$0.00	
1261889	Scheduled service 2000 hr Level B Service		3/03/2020	Internal	4031.0	\$0.00	Subcontractor - Broome Diesel attended site and completed a 2000hr service. Job Completed

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1280496	High revs: Revs to maximum all the time. (SF email)		28/02/2020	Internal	4040.0	\$0.00	Subcontractor - Broome Diesel attended site and repaired the throttle Job Completed.
1276623	Hydraulic leak - SF Email.		12/02/2020	Internal	2989.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1275187	REFURB CENTURION		6/02/2020	Internal	4086.0	\$0.00	<p>Carry out equipment condition assessment</p> <p>Steam clean equipment as necessary.</p> <p>Replace Hi Vis Tape,</p> <p>Replace LPG Bottle bracket as required,</p> <p>Prepare For Hire - Workshop</p> <p>Remove Fleet Management System as required,</p> <p>Fit Fleet Management System as required,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Adjust Fleet Management System as required,</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Repair Light Circuit as required,</p> <p>Replace Lift Chain,</p> <p>Carry out Inspection and Diagnosis of Mast/Carriage</p> <p>pds>>> remove primary chains .. cut new chains to length,,</p> <p>Remove ancillary items, prepare and Paint unit as required,</p> <p>Install Hi Vis Tape,</p> <p>Install Stickers,</p> <p>Paint tynes. install hi-vis tape. install stickers.</p> <p>Replace Seat,</p> <p>Repair Seat Switch Wiring,</p> <p>Adjust Lift Chain to correct specification,</p> <p>Replace Battery,</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485	Description: YALE GDP25TK FORKLIFT						
Make: YALE				Serial No.: B871R12776M			
							Carry out Inspection and Diagnosis of Attachment
							continue job on unit. replace lift chains.. and adjust primary including secondary chains. undo anchors ... verify parts ordered. borrowed lexan roof from another unit. and install. remove seat .. and install a new one.. replace side mirror, and few small parts. on unit.. electrical job done on seat.
							Repair Load Guard as necessary,
							Repair Carriage as necessary,
							Refit Forks/Tynes and ancillary items,
							Remove ancillary items and Load Guard, inspect and report,
							Refit Load Guard and ancillary items,
							Adjust fan belt as required
							Paint hire number. paint touch-up mast and carriage. install tynes. repair removed broken bolt at the carriage and fork positioner. paint touch-up red color battery isolator. adjust fan belt.
							Adjust Carriage to correct specification,
							Repair Linkage/Lever as required,
							Carry out Inspection and Diagnosis of Brake System
							Remove wheel/s, Remove Brake drum/s,
							pds >>> continue adjusting the lift chains.. due to unbalance slack on primary and secondary even on leveled adjustment, so take a thorough measurements of ground clearance. etc. and adjust accordingly,, adjust hose slack as well,, operate machine, heat up hydraulic system,, and found a leak is present on the. fork positionerLH..>>> repair ,/replace bushing on all lever linkages. remove whole assembly due to stuck worn bushings, and ..assembly requires a proper clean up.. painted. lever linkage cover,, re assemble ,, and test.
							Replace Brake master cylinder,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001 Equip. Code: H14485 Description: YALE GDP25TK FORKLIFT Make: YALE Model: GDP25TK Serial No.: B871R12776M							
							Replace Brake Wheel Cylinders, Refit Brake drum/s and refit Wheel/s, Replace Handbrake Cable, Replace Brake adjuster/s, Replace brake shoe/s, overhaul both sides brakes replace cylinder. remove and install associated components.. still waiting on.. hub seals and RH hand brake cable. Install Fire Extinguisher, Repair Light/s pds..install fire extinguisher brackets drill holes for mounting etc.. repair light and light brackets.. Replace Brake hub seal/s, Block up unit, Adjust brakes and handbrake, Overhaul Brakes components as required, continue brake overhaul on unit. install hub seals adjust brakes.. balance brake adjustment.. Flush brakes, Bleed Brake System Replace Attachment Cylinder, CONTInue job on unit bled brake system and verify the problem with un balanced and brake to soft issue... adjust everything required test unit,, bled a few time bed in brake shoes adjust ,, until unit is fit for operation,.. clean up unit, and prepare for hire,... replace fork positioner cylinder
1274743	electrical problem and I think it is with the seat sensor as we have all lights but won't start. - Sf Email	601SUBC	5/02/2020	Internal	2989.0	\$0.00	
1271998	Centurion Broome - Refurn Unit	601WORKSHOP	23/01/2020	Internal	2989.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1266113	replace the battery as it is flat and won't start, I have had it jump started twice today and the battery won't hold charge - Sf Email		23/12/2019	Internal	2989.0	\$0.00	
1260330	Keeps blowing a main fuse, requested Reen Auto to attend, urgent - SF Email.		2/12/2019	Internal	2989.0	\$0.00	
1255868	Replace all tyres. SF Email.		14/11/2019	Internal	2989.0	\$0.00	
1252196	Unit wont start, urgent		31/10/2019	Internal	2989.0	\$0.00	
1232611	job raised for SubCon labour charges		14/08/2019	Internal	2989.0	\$0.00	
1229409	Registration Renewal - 1GPU383		1/08/2019	Internal	2989.0	\$0.00	
1225073	replace wheel studs		16/07/2019	Internal	2989.0	\$0.00	
1214175	Replace brake master cylinder		7/06/2019	Internal	2989.0	\$0.00	Replace brake master cylinder
1198347	Will not start, battery has plenty of life fuses appear to be ok but there is no ignition lights when you turn the key on.		3/04/2019	Internal	2989.0	\$0.00	Will not start, battery has plenty of life fuses appear to be ok but there is no ignition lights when you turn the key on. DR - Subcontractor - Fields - attending site today - 03/04 - customer updated. DR - Subcontractor requested to re-attend site today 01/05 - liaising with Di and Stuart - replacement unit has been prepper for customer.
							TRAVEL TO CENTURION SITE. CHECK SEAT BELT FAULT AS REQUESTED. REMOVE AND CLEAN SEAT BELT BUCKLE. TEST OPERATION. SEAT BELT BUCKLE WORN. RETURN TO WORKSHOP. GO BACK TO CENTURION YARD AND CHECK FORK NOT STARTING. CHECK BYPASSED SEAT BELT SWITCH. CHECK SEAT PRESSURE, PAD OKAY. CHECK SWIPE PAD, FOUND TO BE WITH THE SEAT BELT SWITCH. ADVISED CUSTOMER ON HOW TO START AND STOP FORK EACH TIME. RETURN WHEN PARTS ARRIVED AND REPLACE SEAT BELT BUCKLE. CHECK OPERATION, OK.
1149141	Front Tyre Replacment/Exchange Rims - return Old ones to Interfit.		1/10/2018	Internal	113.0	\$0.00	Full Tyre Set Required Exchange Rims - return Old ones to Interfit.
1135989	RE-REGISTER UNIT/ BUSHES/STEER PINS.		9/08/2018	Internal	1977.0	\$0.00	RE-REGISTER UNIT TO AAL INSPECTION FEE RE-LICENSE FEE
1209493	Scheduled Service - Level B Service		5/08/2018	Internal	3451.0	\$0.00	Scheduled Service -
1126683	1000Hr Service Level B Service		5/07/2018	Internal	1977.0	\$0.00	1000Hr Service

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14485		Description: YALE GDP25TK FORKLIFT					
Make: YALE		Model: GDP25TK		Serial No.: B871R12776M			
1120038	The drive tyres on FL2502 are solids and need replacing as they are worn where it has become difficult to drive onto the fork trailer. the tyres will need to come up from Perth already on rims		13/06/2018	Internal	1977.0	\$0.00	The drive tyres on FL2502 are solids and need replacing as they are worn where it has become difficult to drive onto the fork trailer. the tyres will need to come up from Perth already on rims
1118583	Flat steer tyre. Can I please have a spare tyre placed at the branch as we start at 4am each morning and situations like these put us back 2 hours on deliveries and load outs.		8/06/2018	External	1977.0	\$1,250.30	Flat steer tyre. Can I please have a spare tyre placed at the branch as we start at 4am each morning and situations like these put us back 2 hours on deliveries and load outs.
1108692	Unit will not start, I changed the fuse and tried to jump start. I need this fixed ASAP as this is the only fork at the branch		7/05/2018	Internal	1977.0	\$0.00	Unit will not start, I changed the fuse and tried to jump start. I need this fixed ASAP as this is the only fork at the branch
1099275	Replace steer tyres 6.00x9 pne		3/04/2018	Internal	1977.0	\$0.00	Reaplace steer tyres 6.00x9 pne
1089903	Unit has a flat battery. Site contact Michael Dennis 0419 045 401		26/02/2018	Internal	1977.0	\$0.00	Unit has a flat battery. Site contact Michael Dennis 0419 045 401
1068946	One steer tyre required. - Pneumatic - 6.00-9		30/11/2017	Internal	1903.0	\$0.00	Called out to Tarunda IGA due to flat battery. Replaced the faulty battery. One steer tyre required. - Pneumatic - 6.00-9
1064371	500hr Service on unit 2502		15/11/2017	Internal	1903.0	\$0.00	500hr Service on unit 2502
1052580	Investigate and repair accelerator issue - Sublet Broome		6/10/2017	Internal	0.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Remove and Replace Reverse buzzer, Refit to unit, Carry out 500hr service. Replace reverse alarm. Investigate and repair accelerator issue - Sublet Broome
Equipment Total:						\$2,255.53	
Customer Total:						\$2,255.53	