

Service History Listing Active Units

Date: 10/06/2026

Time: 4:15:19PM

For Equipment Code From: H14742 To: H14742

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001 Equip. Code: H14742 Description: YALE GDP25TK Make: YALE Model: GDP25TK Serial No.: B871R13405M							
1824524	get operational & clean for Auction		8/05/2026	Internal	1403.0	\$0.00	Steam clean equipment as necessary. Carry out equipment condition assessment found machine test drove some hoses need placing. fork track works installed new battery. greased machine. machine is operational. ready for auction. see photos.
1715022	Scheduled Service - ZEL - IC 500Hr SM .0500 Hour Service		22/07/2025	Internal	1390.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Travel to site. Use air to blow unit free of dust and debris. Carry out 500Hr service with supplied filters as per service matrix. Lubricate chain and grease all points. Measure tynes and chain. Bleed diesel system and start the forklift. Carry out a full function test. Double check all levels. Go through unit for any faults or wear. COMPLETE.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001 Equip. Code: H14742 Description: YALE GDP25TK Make: YALE Model: GDP25TK Serial No.: B871R13405M							
1679055	FW 1678257: Front Tyne hoses are worn and will need replacing soon.		16/01/2025	Internal	1263.0	\$0.00	Travel to site, Remove ancillary items and Hydraulic Hose/s, inspect and report, Labour Refit Hydraulic Hose/s and ancillary items, Travel to site. Remove hoses and travel to Pirtek, hose fittings are not available and will only be in stock tomorrow. Travel back to site and re-fit old hoses as forklift can not be booked down for the rest of the day. Travel back to workshop. WORK IN PROGRESS. Replace Hydraulic Hose/s and ancillary items, Travel to site. Remove hydraulic hoses and take them to pirtek for replacement. Drive back to site and replace hoses. Start and test the truck for no leaks. No leaks present. Travel to workshop.
1678257	Scheduled Service - BB IC 1000HR SM .1000 Hour Service		5/12/2024	Internal	1260.0	\$0.00	COMPLETE. 1000hr Service Complete 1000HR service as per matrix with supplied filters, grease all points + lube carriage/lift chains, test all operations + test drive JOB COMPLETED -Mast hoses are all worn and will require replacing at next service -Seat cover missing 1000Hr service. Locate truck and carry out 1000Hr service as per service matrix with supplied filters. Lubricate chain and grease all points. Bleed diesel system and start Truck. Do a full function test. Front Tyne hoses are worn and will need replacing soon. COMPLETE.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1677311	Split hydraulic hose, leaking fluid - Etk# 952408		2/12/2024	Internal	1260.0	\$0.00	Remove ancillary items and Hydraulic Hose/s, inspect and report, Labour Replace Hydraulic Hose/s and ancillary items, R/R fork positioner hydraulic hose, travel to Pirtek and collect fabricated hose JOB COMPLETED Travel to site,
1671997	Forklift is cutting out and losing drive power - tagged out etkt#932563		12/11/2024	Internal	1243.0	\$0.00	Remove ancillary items and Fuel Filter and Replace, Refit Fuel Filter and ancillary items, Check/Inspect/Diagnose Fuel system, bleed Fuel system to remove air, Travel to customer site and inspect unit, found fuel filters were blocked and diesel was contaminated to a yellow colour, air filter was also very dusty/ blocked from yard dust as well as engine bay area, clean engine bay area was air, replace air filter + replace both fuel filters/ bleed fuel system, start and operate machine for extended time, no issues when operating, fuel contamination is not severe but customer will need to keep an eye on as fuel condition could cause machine to fault again and may require full fuel sytem + fuel tank clean, return travel to w/s
1601227	Scheduled Service - KM IC 500hr SM - 4500hrs .0500 Hour Service		10/07/2024	Internal	1195.0	\$0.00	JOB COMPLETED Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Complete 500HR service as per matrix with supplied filters, grease all points + lube carriage/ lift chains, test all operations + test drive JOB COMPLETED

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1591993	*COMPLETED - WAITING ON INVOICE* TYRES ORDERED 15/01/24 *All 4 tyres to be replaced. Etk 631003		28/03/2024	Internal	1156.0	\$0.00	Carry out equipment condition assessment Travel to site, Check over tyre condition on unit, liason with OTR tyres and coordination team will have to liason with them for a book in time for fitment and replacement of 2x 28-9x15 solids and 2x 6.00x9 solids, return travel to w/s ON HOLD 12/1/24 Replace Wheel/s, Travel to site and collect unit, drive unit to OTR tyres for tyre replacement, walk back to sealanes to collect truck,was on hold all day due to background delays, return at end of day and only fronts have been completed, rear set will be finished on monday morning Labour Collect unit from OTR and drive unit to Sealanes and then walk back to OTR
1603352	Forklift not working-Tagged Out-URGENT-ETKT-673589		26/02/2024	Internal	1146.0	\$0.00	JOB COMPLETED Travel to site, Carry out equipment condition assessment . Found that battery was not functioning and requires replacing, travel to Jolly Goods and collect battery, return to site and fit new battery JOB COMPLETED

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1591943	Leaking fluids from hydraulic hoses. Etk 630809		17/01/2024	Internal	1124.0	\$0.00	<p>Travel to site,</p> <p>Repair Sideshift as necessary,</p> <p>Travel to customer site and inspect oil leak , remove side side shift cylinder and clean + inspect, will require side shift cylinder seal kit to be ordered as wiper seal has fallen apart on one side, refit side shift cylinder and refit hoses + clean carriage, relube carriage as it was abit dry and check hydraulic oil level</p> <p>PARTS TO BE ORDERED VIA PARTS FROM OEM 12/1/24</p> <p>PHOTOS ATTACHED OF DATA PLATE</p> <p>Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,</p> <p>Travel to Sealanes and inspect leak on carriage , found that the fittings that feed the fork positioner assembly were loose and required tightening, tighten and test operation (no leaks), reurn tavel to w/s</p>
1508216	*ORDERED SM KIT - 24/08/23* Scheduled Service - KM IC 4000hr SM - 4000hrs .4000 Hour Service		21/09/2023	Internal	1051.0	\$0.00	<p>JOB COMPLETED 4000hr Service,</p> <p>Travel to customer site, complete 4000HR service as per matrix with supplied filters, grease all points + lube carriage/lift chains, test all operations + test drive</p> <p>JOB COMPLETED</p>
1534803	Forklift will not start / No ignition .Etk 416793		15/05/2023	Internal	980.0	\$0.00	<p>-All tyres are about 60% health (photos attached)</p> <p>Travel to site,</p> <p>Replace Battery,</p> <p>Travel to site, sign in with admin, locte unit on site, check unit for no go, found battery was flat, juump start machine and check charge rate all okay, load test battery and battery failed, go get a new battery, fit new battery and test drive machine all okay. JOB COMPLETE</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1508178	Seat belt needs replacing - URGENT -ETCK #308268		18/01/2023	Internal	1029.0	\$0.00	<p>Repair Seat as necessary, BREAKDOWN</p> <p>Told by customer that seatbelt clip had broken and needed replacing, found correct model seatbelt clip in W/S, install on site, rewire jumper connections back to correct plug, test operation (all OK)</p> <p>*Will need to order part as seatbelt clip must have been off of an old asset</p> <p>Seatbelt was replaced on 18/1/23</p>
1461652	Scheduled Service - AL - 2000hr service .2000 Hour Service		5/07/2022	Internal	777.0	\$0.00	<p>JOB COMPLETE</p> <p>Travel to site and carry out 2000HR service.</p>
1422920	The seatbelt buckle has wrecked and they can't start the forklift. Tagged Out. URGENT.	602SUBC-FIXI001	23/12/2021	Internal	603.0	\$0.00	<p>Repair leak on fork positioner.</p> <p>Subby - Fixify attended site:</p> <p>TRAVEL TO SITE.</p> <p>SIGN IN.</p> <p>CHECK FORKLIFT.</p> <p>MODIFIED SEAT BELT BASE.</p> <p>REPLACE NEW SEAT BELT.</p> <p>TEST AND START, ALL GOOD.</p> <p>REQUEST CUSTOMER TO CONFIRM TO START</p> <p>CHECK, ALL GOOD.</p> <p>SIGN OFF.</p> <p>TRAVEL BACK</p> <p>Job Complete</p> <p>Labour</p>
1407270	Scheduled Service - AL - 500hr SM - 1500hrs 0500 Hour Service		26/10/2021	Internal	603.0	\$0.00	<p>Travel to site,</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Pick parts from yard, travel to site, Carried Out 500HR Service, grease all grease points, lube chains and carriage, measure chains and tynes all okay, remove and replace engine oil and oil filter, check all oil levels all okay, check all lights all okay. JOB COMPLETE</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1399608	Hydraulic Leak - URGENT - SF EMAIL		2/09/2021	Internal	576.0	\$0.00	Travel to site, Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Labour Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Travel to site, check over unit for oil leak, found side shift fitting had been snapped off, travel to Pirtex to get new fittings, travel back to site, fit new fittings, degrease down machine and test drive all okay, check oil levels all okay. JOB COMPLETE
1374874	Scheduled Service - 1000hr SM - 1000hr SM Interval .1000 Hour Service		10/05/2021	Internal	478.0	\$0.00	Travel to site, 1000hr Service Carried Out 1000HR Service, grease all grease points, lube chains and carriage, measure chains and tynes all okay, remove and replace engine oil and filter, replace fuel filters, replace air filters, check all oil levels all okay, check all lights all okay. JOB COMPLETE
1368126	Blown Hydraulic Hose - Time Amendment Kimmy for 30/03/21	601SUBC	5/04/2021	Internal	424.0	\$0.00	
1367463	Blown a hydraulic hose		30/03/2021	Internal	424.0	\$0.00	Travel to site, Replace Hydraulic Hose/s and ancillary items, Labour Steam clean equipment as necessary. travel to site, sign in with admin, locate unit, check blown hydraulic hose, found the hose leak from side shift, remove hose from side shift, take to Pirtex to be made up new hoses, wait for hose to be made, pick up the hose travel back to site, re-fit the hoses, check oil level top up as require, wash down unit, test operate unit, check for leak all ok. Job complete

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
---------	-------------	----------	------	----------	----------	--------	-------

Owner: ADAP001

Equip. Code: H14742

Description: YALE GDP25TK

Make: YALE

Model: GDP25TK

Serial No.: B871R13405M

1363916	FW: Lights not working, Breaks need adjusting and belt needs to be adjusted & fuel cap needs to be replaced		12/03/2021	Internal	579.0	\$0.00	<p>Adjust fan belt as required Block up unit, Adjust brakes and handbrake, Repair Light/s Fuel cap needs to be replaced as it is not sealing will order new one, adjust fan belt as required, adjust brakes and handbrake lever as required, remove all packing strap from around brake drums, headlights not working, check all fuses, check for globes all okay, check power at plugs found plugs had corroded, cut off plugs and fit new plugs. assist Adrian</p> <p>Travel to site,</p> <p>Carry out Inspection and Diagnosis of Brake System</p> <p>Travel to site, check over unit for fuel cap issues, customer found fuel cap so no need to new one now, check belt tension all okay, check brakes found no problems with them. JOB COMPLETE All parts need to be removed from this job. Fuel Cap never arrived, and camera kits are for a different job.</p>
1363226	Scheduled Service - AL - 500hr service .0500 Hour Service		12/03/2021	Internal	411.0	\$0.00	<p>Travel to site,</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Travel to site, sign in with admin, Carried Out 500HR Service, grease all grease points, lube chains and carriage, measure chains and tynes all okay, remove and replace engine oil and oil filter, check all oil levels all okay, check all lights all okay. JOB COMPLETE</p> <p>assist Adrain.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1334340	CW - Leaking/broken side shift fittings - Photo sent to SC - SF Email.		16/10/2020	Internal	290.0	\$0.00	<p>Travel to site,</p> <p>Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,</p> <p>Labour</p> <p>Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,</p> <p>Travel to site, sign in with admin, locate unit, check for hydraulic leak, found side shift hose connections had come loose and damaged the threads, remove connectors, travel out to pirtek to get 2 new connectors, travel back to site, fit new connectors, test out hydraulic functions and check for leaks none found, clean down unit all okay, top up fluid as required. JOB COMPLETE</p>
1325922	Scheduled Service - RH. 1000Hr service .1000 Hour Service		9/09/2020	Internal	267.0	\$0.00	<p>Travel to site,</p> <p>1000hr Service</p> <p>Travel to site, carried out 1000HR service, replace engine oil, oil filter, fuel filter and air filter, grease all grease points, lube chains and carriage, measure chains and tynes, check all other oils and coolant, check tyre condition and adjust tyre pressures. JOB COMPLETE Dont Close Until Parts Are On Job.</p>
1318172	CW-Unit is not starting, battery possibly needs to be replafced. Located in the LIA. SF Email. Site contact- Kane 0447 986 549		4/08/2020	Internal	250.0	\$0.00	<p>Travel to site,</p> <p>Remove ancillary items and Remove Battery from unit and Inspect and report,</p> <p>Labour</p> <p>Refit Battery to unit, Refit ancillary items,</p> <p>Travel to site, check over unit for no go, found battery was flat, load test battery, travel to get new battery from Jolly Goods, fit new battery, start unit and check charge rate all okay. JOB COMPLETE</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1223351	Prep Machine for Hire		10/07/2019	Internal	124.0	\$0.00	<p>Prepare For Hire - Workshop</p> <p>Remove ancillary items and Mast, Strip, Inspect and report,</p> <p>Refit Mast and ancillary items,</p> <p>Remove Fleet Management System as required,</p> <p>Install Fleet Management System (Basic),</p> <p>Refit Dashboard and ancillary items,</p> <p>Adjust Fleet Management System as required,</p> <p>swapped mast,swapped telsys,prep for hire,swapped rear tyres,</p> <p>Prepare For Hire - Workshop</p>
1204205	fleet inspection		30/04/2019	Internal	124.0	\$0.00	<p>Locate unit</p> <p>Fleet inspection as required, unit in good condition</p> <p>No further work</p> <p>service</p>
1183117	service		7/02/2019	Internal	68.0	\$0.00	<p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p>
1183115	PREP FOR HIRE QUENBY pneumatic tyres and standard forks Please take photos **Units without speed limiting would be great too, as quite often we are driving the units form site to site, up to 10km.		7/02/2019	Internal	68.0	\$0.00	<p>Carried out 500hr service.</p> <p>PREP FOR HIRE QUENBY pneumatic tyres and standard forks Please take photos **Units without speed limiting would be great too, as quite often we are driving the units form site to site, up to 10km.</p> <p>Prepare For Hire - Workshop</p>
1156295	DEHIRE CHECK MACHINE FROM KAL EXPRESS		25/10/2018	Internal	76.0	\$0.00	<p>Prep for hire.</p> <p>Carry out equipment condition assessment</p> <p>Steam clean equipment as necessary.</p> <p>Grease All Points on Unit,</p> <p>Air vent on overhead guard missing.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1153635	pREP FOR HIRE		16/10/2018	Internal	71.0	\$0.00	Prepare For Hire - Workshop carried out prep for hire on unit, checked all electrical and hydraulic functions, checked and topped up fluids as required. greased mast and adjusted components as required.
1149749	DEHIRE CHECK MACHINE FROM CCA ROYAL SHOW		2/10/2018	Internal	59.0	\$0.00	Carry out equipment condition assessment Steam clean equipment as necessary. Grease All Points on Unit, Replace Stickers, Minor body paint damage on counter waight,Recomend steam clean & Need do instal damage stickers.
1145095	REPLACE FRONT TYRES		13/09/2018	Internal	29.0	\$0.00	REPLACE FRONT TYRES
1144441	Prep for Hire - CCA Royal Show		11/09/2018	Internal	29.0	\$0.00	PREP MACHINE FOR HIRE PHOTOS TO BE TAKEN DIESEL FILLED PLEASE ENSURE MACHINE LOOKS TIDY GONIG TO ROYAL SHOW Prepare For Hire - Workshop Carried out prep for hire. Filled diesel. Tynes 0% worn. Chains 0% worn. Ops manual missing. Requires front tyres.
1114973	Dehire unit, check fuel use, custome damage		28/05/2018	Internal	25.0	\$0.00	Please paint tynes Prepare For Hire - Workshop De-hire check over as required. Customer damage- Opperators manual missing

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1107736	Prep for hire to onsite		2/05/2018	Internal	12.0	\$0.00	Fit ti unit, <ul style="list-style-type: none"> - E-stop - Isolation switch - High vis - Fire extinguisher - Beacon Carry out equipment condition assessment Prepare For Sale - Workshop Front tyres incorrect Install Battery Isolator, Fit Emergency Stop to unit, Install Fire Extinguisher, Install Hi-Vis Tape, Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Carried out pre-hire checks. Installed e-stop. Installed battery isolator. Replaced battery. Installed fire extinguisher. Applied hi-vis tape.
1096268	2584 - Air con is warm and is struggling through the day		20/03/2018	Internal	11.0	\$0.00	2584 - Air con is warm and is struggling through the day

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H14742		Description: YALE GDP25TK					
Make: YALE		Model: GDP25TK		Serial No.: B871R13405M			
1084763	prep for STR ready - AAL stickers, hire number		7/02/2018	Internal	11.0	\$0.00	<p>prep for STR ready - AAL stickers, hire number</p> <p>Prepare For Sale - Workshop</p> <p>Repair Steering Column as required,</p> <p>Replace Battery,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Carry out New Equipment Predelivery to correct specification.</p> <p>Steam clean equipment as necessary.</p> <p>Remove ancillary items and Mirror and Replace, Refit Mirror and ancillary items,</p> <p>Refit Load Guard and ancillary items,</p> <p>Remove ancillary items and Forks/Tynes, Inspect and report,</p> <p>Replace Lift Chain,</p> <p>Adjust Lift Chain to correct specification,</p> <p>Prepare For Hire - Workshop</p> <p>Strip and Repair Contactor, Reassemble,</p> <p>Refuel Unit</p> <p>Remove and Replace Reverse buzzer, Refit to unit,</p> <p>replaced rev buzzer,</p>
Equipment Total:						<u>\$0.00</u>	
Customer Total:						<u>\$0.00</u>	