

VPM03 – 1EHT 073

- **02/01/2018 – 561,877 km**
 - Cummins replaced engine liners, piston rings, big end bearings and main bearings. Turbo replaced.
- **15/03/2019 – 704,157 km**
 - Cummins completed Level 2 mid-life rebuild:
 - Engine brake spools and springs replaced
 - Water pump replaced
 - AdBlue injector replaced
 - Fan belt and tensioner replaced
 - A/C belt and tensioner replaced
 - Air compressor replaced
 - Coolant thermostat replaced
 - A/C high-pressure line into compressor replaced
- **15/07/2019 – 743,543 km**
 - Clutch replaced. Rear suspension airbags replaced. Front steer shock absorbers replaced.
- **27/08/2019 – 759,017 km**
 - NOx sensor replaced.
- **28/01/2020 – 819,516 km**
 - Drive axle brake shoes, hardware kits and brake drums replaced.
 - Turntable rebuilt.
 - Airline replaced from air compressor to air dryer.
 - Clutch adjusted.
- **10/05/2021 – 956,614 km**
 - New alternator fitted. Alternator belt replaced. Two new engine mounts fitted to ice pack.

- **09/03/2022 – 1,031,685 km**
 - Front engine mounts replaced. RHS windscreen replaced.
- **18/07/2022 – 1,062,633 km**
 - A/C evaporator replaced.
 - Turntable rebuilt.
 - LH steer king pin replaced.
 - A/C repaired.
 - Wiper jets repaired.
 - RH windscreen replaced (AAA).
 - Wheel alignment completed by Tyre Savers.
- **08/05/2023 – 1,103,874 km**
 - Engine brake assembly overhauled due to elongated rocker shaft detent.
 - Both rocker shafts replaced and engine brake overhaul kit installed.
 - Fuel pump head replaced (cracked head and pressurizing plunger fault).
 - Exhaust manifold gaskets replaced.
- **08/08/2023 – 1,122,298 km**
 - Clutch replaced. Rear gasket between bell housing and engine block replaced. Universal joints replaced.
- **18/06/2024 – 1,168,039 km**
 - Engine Horton fan replaced.
- **21/02/2025 – 1,180,020 km**
 - Cummins replaced turbo, SCR catalyst and ECU.
- **30/08/2025 – 1,198,304 km**
 - Transmission cables replaced (tight).
- **17/09/2025 – 1,199,958 km**
 - Four starting batteries replaced.